





Assembly Instructions

2410MC



Parts List

lable	Picture	Description	Qty
A			1
B		This fittings have two screw hole in both side.Put the bigger screw hole inward and the small screw hole outward	2
C			1
D			2

Hardware List

lable	Picture	Description	Size	Qty
H-1		Bolt	M6x55 mm	8
H-2		Bolt	M6x25 mm	4
H-3		Bolt	M6x15 mm	4
H-4		Middle axle	φ6x14 mm	4

Tool List


lable	Picture	Description	Size	Qty
T-1		Allen Key	φ4 mm	1

Assembly Steps


ATTENTION:

DO NOT COMPLETELY TIGHTEN ANY SCREWS UNTIL ALL PARTS ARE IN PLACE


Step 1



Step 2



Step 3



Step 4

